


# Garrett Wade

## Technical Memo T21

Re: 23N02.01 23N02.02 23N02.10



**Special Note:** Sometimes the screwdriver end on the scribe does not fit the slot of the pivot screw. This can be easily corrected with a small file by removing any burrs left on the tip from the machining process. Simply filing the flats of the tip a few times will correct the problem.

For further assistance, call the Garrett Wade Technical Department at 800 221 2942, or email us at [mail@garrettwade.com](mailto:mail@garrettwade.com)