

# IMPORTANT SAFETY RECALL

## Porter-Cable 7518, 7519, 7519EC and 22-7519-60 Routers Porter-Cable 75361 Router Bases

Porter-Cable has identified a safety issue with the bases on some 3-1/4 HP fixed base production routers. The router base does not have insulated gripping surfaces, and could present a shock hazard.

### The following models are affected:

Porter-Cable Speedmatic 3-1/4 HP Five-Speed Router Model 7518

Porter-Cable Speedmatic 3-1/4 HP Router, Model 7519

Porter-Cable Speedmatic 3-1/4 HP Router with extended chuck, Model 7519EC

Porter-Cable Speedmatic High Voltage 3-1/4 HP Router, Model 22-7519-60


Porter-Cable Router Base, Model 75361

Affected models have date codes before 2014 14 and have uninsulated handles on the base.




The model number can be found on the nameplate of the motor or bare base. The date codes can only be found on the motor nameplate.

Model Number



Date Code



The improved base will be readily identifiable by the insulated gripping surface on the handles.

If your router or base is affected, STOP USING IT IMMEDIATELY, and call toll free

**1-888-344-7973**

between 8 a.m. and 6 p.m., Eastern Time, Monday through Friday,

or e-mail: [support.portercable@sbdinc.com](mailto:support.portercable@sbdinc.com) for information about a free replacement router base.